

FIG. 1A
(PRIOR ART)




FIG. 1B
(PRIOR ART)




FIG. 2A




FIG. 2B




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 6A




FIG. 6B

Acoustic events during a complete adjustment cycle




FIG. 7A

Click signals during a complete adjustment cycle




FIG. 7B

Bang signals during a complete adjustment cycle




FIG. 7C

Bang signals over time




FIG. 8

Click signals over time




FIG. 9

Acoustic events over time




FIG. 10